

LEXCAN

# Weathered Membrane Cleaner

## DESCRIPTION & USE

Lexcan Weathered Membrane Cleaner is a solvent used to clean both new and in-service EPDM membrane and TPO membrane prior to the bonding process. It helps to loosen and remove dirt and other contaminants from the surface of the membranes and leaves a suitable surface for welding or the subsequent application of adhesive.

## FEATURES & BENEFITS

- Cleans new and in-service EPDM and TPO membranes
- Helps to loosen and remove dirt and other contaminants from membrane surfaces
- Gentler to membranes than other available solvents

## TECHNICAL DATA

Physical Properties	
Colour	Clear
Solids	0%
Flash Point	18°C (65°F)
Boiling Point	127°C (260°F)
VOC	755 grams / litre
Packaging	18.9 litre (5 gallon) closed top pail & 2 x 3.8 litre (1 gallon) closed top pail

### Coverage Rates

Depends on the age of the membrane and the amount of dirt and debris on the surface. Assume 400 square feet (37.2 square meters) (one surface) per 3.8 litres (1 gallon).

## CAUTIONS & LIMITATIONS

- In case of fire handle as a solvent or gasoline fire. Use dry chemical, carbon dioxide or foam fire extinguishers. Water fog or spray may be used to smother the fire and cool containers. Do not use a solid stream of water to fight fire because it can scatter and spread the fire.
- See MSDS for complete safety information before using product.



## APPLICATION INSTRUCTIONS

1. Use solvent resistant gloves when handling product.
2. Excessively dirty membrane will require pre-cleaning with a household cleaner such as Spray-Nine prior to using Lexcan Weathered Membrane Cleaner.
3. Clean all mating surfaces by saturating cleaning cloths with Lexcan Weathered Membrane Cleaner.
4. Wipe the area to be cleaned until it is a consistent color with no streaking.
5. Change cleaning cloths frequently so as not to re-deposit dirt.
6. Allow surfaces to dry before hot air welding or application of adhesive.